

CCHS – Envelope Story Board



The sports hall is traditionally built. At Clacton the steel frame requires cladding. This cladding is an insulated panel and fixed to the steel frame.



On top of the modules a parapet has been installed to provide a edge protection for operatives that undergo maintenance on the roof. It also acts as a barrier with the services on top of the roof and pedestrians below.



On the north elevation of the sports hall all of the windows have been successfully installed using cherry pickers that work within a exclusion zone to keep everyone safe on site .